


HYUNDAI I45, KIA OPTIMA (TF)

FILTER IS LOCATED BEHIND THE GLOVE BOX

WORK PROCEDURE

- 1 The housing is located behind the glove box. To access the housing the glove box will have to be removed. First release the strut which is located on the left hand side. It simply clips out.
- 2 Once strut is released proceed to remove securing clips on both sides and gently pull forward the glove box as if opening it and it will drop.
- 3 At this point the housing can be easily identified. It will be sitting on top of the blower fan.



STEP 1



STEP 2




STEP 3

HYUNDAI I45, KIA OPTIMA (TF)


FILTER IS LOCATED BEHIND THE GLOVE BOX

WORK PROCEDURE

- 4 Once the housing has been identify proceed to remove the lid by presing together the plastic clip on the right hand side. Gently pull it and slide it to the right and it should come off easily.
- 5 Remove the old filter and clean housing from residual dirt. Insert the new filter in the right air flow direction (as indicated). Look on the side of filter to identify fitting direction. Re-fit all components in reverse order.



STEP 4



STEP 5