




FITTING INSTRUCTIONS FOR RYCO CABIN FILTER RCA290P. HYUNDAI ACCENT (MC)



- 1. The cabin air filter is located behind the glove box compartment. To gain access to the cabin air filter the unit requires removal.
- 2. For better working space, slide the passenger seat all the way back. Open the glove box, remove both top corner retaining lugs from the inside of the box so the lid can be dropped completely.
- 3. Identify the cabin air filter housing and unclip the lid from the top section and remove. Slide the old cabin filter out carefully to avoid any accumulated debris from being spread around and clean the area.
- 4. Slide in the new filter making sure it faces the correct air flow direction. Refit all components in reverse order.

Ryco Group Pty Ltd 29 Taras Ave Altona North Victoria 3025 Australia. www.rycofilters.com.au RYCO Group A division of GUD NZ Holdings Ltd 626A Rosebank Road Avondale Auckland, New Zealand www.ryco.co.nz