

- 1: SONATA, Open glove box, press both sides of glove box inward then lower glove box. XG, Open the bonnet and remove the glove box stop then lower the glove box.
- 2: SONATA, remove the lower side instrument panel trim pad, remove the four glove box upper cover retaining screws then the cover, remove the two glove box retaining bolts then remove the glove box. Press on the filter cover tab and remove the cover. XG, Remove the two glove box retaining bolts then the two retaining screws then the glove box. Remove the lower side instrument panel trim pad, disconnect electrical connector, push downwards on the blower unit under cover then remove the cover.
- 3: SONATA, Remove used filter from housing, install new RYCO filter making sure air flow arrow is facing correct direction then replace filter cover. XG, Remove used filter from housing, install new RYCO filter making sure air flow arrow is facing correct direction then replace filter cover, reinstall blower unit under cover and reconnect electrical connector.
- 4: SONATA, Position glove box to instrument panel, install two retaining bolts and glove box upper cover, replace lower side instrument panel trim pad and lift the glove box into position, replace the four glove box upper cover retaining screws then close the glove box. XG, Position glove box to instrument panel, install two retaining bolts and glove box upper cover, replace the lower side instrument panel trim pad, position the glove box to the instrument panel and install two glove box attaching screws, lift glove box into position, replace the stop then close the glove box.

Ryco Group Pty Ltd 29 Taras Ave, Altona North Victoria 3025 Australia. www.rycofilters.com.au Ryco Group A Division of GUD NZ Holdings Ltd 626A Rosebank Road, Avondale Auckland New Zealand www.ryco.co.nz